

UUS INFOALLIKAS ESI[TRONIC] 2.0 KASUTAJATELE

LEIA ÕIGE LAHENDUS SEKUNDITEGA – ISEGI KEERULISTE PROBLEEMIDE PUHUL

The component <Engine management fault lamp> lights. / The component <Glow plug warning lamp> lights.

SIS/CAS **Known Fixes online** Make information General information

The component <Engine management fault lamp> lights. / The component <Glow plug warning lamp> lights.

Complaints:

- The component <Engine management fault lamp> lights.
- The component <Glow plug warning lamp> lights.

General conditions:

- Possible fault memory entries in the component <Engine control unit>:
 - P018100 / Fuel-temperature sensor / Signal improbable
 - P018200 / Fuel-temperature sensor / Short to ground
 - P018300 / Fuel-temperature sensor / Open circuit/positive short
 - P009100 / Fuel shutoff valve / Short to ground
- The following components are in proper technical working order:
 - Fuel-temperature sensor
 - Fuel metering unit

Possible causes:

- The component W1.70 Engine wiring harness is damaged due to vibrations of the component <Engine> near the component B3.8 Fuel-temperature sensor and the component Y28.1 Fuel metering unit.
- The damage to the component <Engine wiring harness> may not be visible from outside.

Remedy:

Check the component <Engine wiring harness> and replace or repair if necessary.

How useful was this information?

Yes Yes, I had this fault and the solution was helpful for me.

EBR EELISED LÜHIDALT

- ▶ Kogemustega Boschi meeskonna poolt loodud ning Boschi ülemaailmse diagnostikakogukonna poolt heaks kiidetud remondijuhised.
- ▶ Juba praegu 500.000 elust võetud juhtumit – ning andmebaas kasvab iga päev!
- ▶ Aega säästev: Tekstitsing võimaldab otsida veakode, sümptomeid ja isegi komponente. Kehtib ka probleemidele, millest ei salvestata veakoodi.
- ▶ Remondiprotsessi lihtsustamiseks sama remondijuhiste struktuur.
- ▶ EBR pakub alati uusimaid lahendusi tänu nõutud internetiühendusele.

UNIKAALNE LAHENDUS TURUL

EBR-leidja

Bosch on loonud innovaatilise algorütmiga, mis võimaldab nõu EBR-leidjal tuvastada erinevatest allikatest esilekerkivaid sõidukite probleeme – selle baasil loovad kogemustega Boschi SIS autorid remondilahenduse.



DETAILIDENI LÄBI MÕELDUD

Tagasiside funktsioon

Tagasiside funktsioon iga juhise lõpus võimaldab sinul ja teistel ESI[tronic] diagnostikaekspertidel hinnata lahendust ja näha lahendusele antud hinnanguid. See näitab, kui populaarne antud lahendus on ja muudab otsingu veel lihtsamaks – tihti kasutatud lahendused on nimekirjas esimestena.

How useful was this information?

Yes

Yes, I had this fault and the solution was helpful for me.

No

I had this fault, but the solution was not helpful.

I had another fault or other symptoms.

Create an ESI[tronic] ticket to report a fault.

VEENDU EBR EELISTES

- ▶ Lisa see unikaalne info oma ESI[tronic] 2.0 lepingule ja muuda oma igapäevane veaotsing lihtsamaks, kui see kunagi olnud on.
- ▶ EBR lepingu eelduseks on TSB (Technical Service Bulletins) lepingu olemasolu. Master pakettis või eraldi.
- ▶ Kui sa pole veel EBR osa tellinud, näed sa siiski kogu andmebaasi nimekirja, aga sisu on lukustatud, kuni EBR litsents on aktiveeritud.
- ▶ Uue EBR lepingu sõlmimiseks võta ühendust kohaliku tarkvaramüüjaga.

Kust leida rohkem infot diagnostikalahenduste kohta...?



Bosch Workshop World

<http://www.bosch-workshop-world.com>

YouTube Channel

<https://www.youtube.com/channel/UCX35lpVGym534NmQoXF8cZw>

Robert Bosch OÜ

Kesk tee 10

Jüri alevik, Rae vald

75301 Harjumaa

Eesti

tehniline.tugi@lv.bosch.com

www.bosch.ee



Balti Autoosad AS

Põrguvälja tee 4F

Rae vald, Lehmja küla

75306 Harjumaa

Tel: +372 6200600

info@autopars.ee



facebook.com/bosch



twitter.com/bosch



youtube.com/bosch